





**TRANSFORMER BOBBIN  
INDUSTRIAL CO.,LTD.**

Tel : 886-2-22929999 Fax : 886-2-22925236  
 http:// tbi-tw.com e-mail : tb6688@ms46.hinet.net


REVISIONS

REV	SYM	DRAFTER	CHECKER	DATE
△		T.S.LII	W.H.HSU	03/15/01
△		T.S.LII	W.H.HSU	05/25/04
△		T.S.LII	W.H.HSU	09/30/05



T=0.3

PART NO.	RM5 SMD CLIP				
DWG NO.	MATERIAL (BOBBIN)	MATERIAL (TERMINAL)	TERMINAL (PLATING)	PIN ALOCATION	BUYER ' S PART NO.
TBI-408-03011.1		△ SK7	△ Sn		



TOLERANCE : .X±0.15 .XX±0.10 .XXX±0.05

UNIT : m/m

SCALE 3.5 : 1

Finish: 1. Immersion gold on terminal : Thickness gold 0.075 μm (3 μ inches) min, Base nickel 0.625 μm (25 μ inches) min.  
 2. Immersion Sn on terminal : Terminal: Sn plating, 100, 5 μm (200 μ inches) min , Base nickel 0.625 μm (25 μ inches) min.  
 3. Coplanarity deviation: 0.10 mm (0.004 inches) max.

REV 3